



CASE STUDY

CUSTOMER

COLOWYO MINE

LOCATION

MEEKER, CO USA / OCT 2009

EQUIPMENT

DISPENSER

APPLICATION

DIESEL FUEL

PROVEN
RESULTSPROTECTED
TIER 3 & 4 ENGINESMINIMIZED
PUMP & INJECTOR
WEAR

CHALLENGE

Out of concern for the new tier 3 and 4 engine tolerances, Colowyo wanted to improve their diesel fuel engine cleanliness to minimize injector and pump wear.

SOLUTION

Install an OEI high-flow magnetic filter scrubber with a contamination holding capacity of over 1200 lbs.

RESULTS

Photos show the contamination collected after filtration of approximately 150,000 gallons of diesel fuel. The filter was installed downstream of the pump to reduce pump component wear, and extend the life of conventional filter elements upstream.

PRODUCT
RECOMMENDATION**MAGNETIC
FILTER SCRUBBER**

403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

